

## "V" BELT SIZES – BY MACHINE

These are FRACTIONAL HORSEPOWER belts (like you would find in a furnace or clothes dryer) and can be found at Lowes/Home Depot or some Hardware/Auto Parts stores.

**We do not carry the clear or round poly belts any more.**

<b>MI-1220 &amp; MI-1220 XL</b>	<b>Size:</b>	<b>Industrial Standard</b>	<b>Item Code:</b>	<b>Price:</b>
			<b><i>K99-172</i></b>	<b><i>\$26.99</i></b>
Mill Head	3/8" x 29"	3L290	C32005A	\$7.25
Lathe – Single Spindle to Motor	3/8" x 36"	3L360	C30109A	\$7.99
Lathe – Double Spindle to Idler, Idler to Motor	3/8" x 23"	3L230	C30137A	\$6.78
	3/8" x 24" (replaces two metric belts that are each 23-1/2" long)	3L240	C38004A	\$6.78

<b>MI-1220 XL/LTD</b>	<b>Size:</b>	<b>Industrial</b>	<b>Item Code:</b>	<b>Price:</b>
			<b><i>K99-173</i></b>	<b><i>\$34.99</i></b>
Mill Head	3/8" x 29"	3L290	C32005A	\$7.25
	3/8" x 40"	3L400	C32022A	\$8.66
Lathe – Single Spindle to Motor	3/8" x 36"	3L360	C30109A	\$7.99
Lathe – Double Spindle to Idler, Idler to Motor	3/8" x 23"	3L230	C30137A	\$6.78
	3/8" x 24" (replaces two metric belts that are each 23-1/2" long)	3L240	C38004A	\$6.78

<b>Granite Classic</b>	<b>Size:</b>	<b>Industrial</b>	<b>Item Code:</b>	<b>Price:</b>
			<b><i>K99-174</i></b>	<b><i>\$30.99</i></b>
Mill Head	1/2" x 37.5" (not sold in stores)	N/A	G05042 ONLY SUPPLIED by SMITHY	\$8.95
Lathe – Single Spindle to Motor	1/2" x 41"	4L410	G03020A	\$9.36
Lathe – Double Spindle to Idler, Idler to Motor	1/2" x 30"	4L300	G02034A	\$7.66
	1/2" x 27"	4L270	G02043A	\$7.25

<b>Granite MAX/I-MAX</b>	<b>Size:</b>	<b>Industrial</b>	<b>Item Code:</b>	<b>Price:</b>
Mill Head	13mm x 1092mm	N/A (metric A-1092)	GMX05127 ONLY SUPPLIED by SMITHY	\$7.25
Lathe – Single Spindle to Motor	13mm x 920mm	N/A (metric A-920)	GMX03020 ONLY SUPPLIED by SMITHY	\$6.99

<b>SuperShop</b>	<b>Size:</b>	<b>Industrial</b>	<b>Item Code:</b>	<b>Price:</b>
ONLY ONE BELT	3/8" x 28"	3L280	SS330	\$5.25